Roof-project photographs: July 10-August 19, 2025

SELECTION

Five original exhibit pages (AA-1 through AA-5) showing containers, stored material and work activity. These are the source author's selected chronology. Some views also appear in the earlier asbestos binder and must not be counted as separate events.

DATE AND SOURCE CHECK

Printed capture times match the EXIF dates and time-zone offsets in the JPEG derivatives embedded in the source PDF. Their checksums match the source index. This confirms consistency within the saved package, not independent authentication of when or where the photographs were taken.

LIMITS

Photographs do not establish asbestos content, disturbance of asbestos-containing material, regulatory status, or events outside the frame. Original exhibit captions are the submitter's descriptions and requests, not agency findings.

LATER AGENCY EXPLANATION

DSHS's September 3, 2026 response says the evidence was insufficient to support a notification violation. It reports the inspector's account that the asbestos-positive flashing was outside the then-current work area. DSHS issued the survey-related NOV. These qualifications must accompany any use of the earlier photo allegations.

COPY HANDLING

Original page numbers are preserved. Hidden image metadata is removed where present; original binders and audit evidence remain private. The complete binder, other exhibits and original image files are outside this selection.

Source: September 3, 2026 evidence addendum, PDF pages 39, 40, 41, 42, 43

Editorial context note. Source exhibits follow.

Plate AA-1: Filled roll-off on July 10



AA-1A - 2025:07:10 18:30:31 CDT



AA-1B - 2025:07:10 18:30:31 CDT

Two views show a gray roll-off with material extending above its rim in a flagged work zone on July 10, one day before the limited survey report. The images do not establish the contents' asbestos status, and no liner is visible in the photographed exterior/upper portions.

Plate AA-2: Stored material and continuing work



AA-2A - 2025:07:12 11:17:38 CDT



AA-2B - 2025:07:16 09:20:53 CDT

The July 12 photograph shows large stacks of dark sheet-like material, partly covered, beside the building. The July 16 photograph shows a telehandler, yellow roll-off, plywood carrier, and roof activity. The sequence documents continuing project conditions after the limited survey, not the composition of the materials.

Plate AA-3: Roll-off, stored material, and open-load transport



AA-3A - 2025:08:03 09:14:31 CDT




AA-3B - 2025:08:03 09:14:47 CDT

August 3 views show a maroon roll-off beside stacks of removed sheet-like material and a telehandler carrying an open load near grocery receiving. They document the method and location of material handling but do not identify the material as asbestos-containing.

Plate AA-4: Multiple containers and roof activity



AA-4A - 2025:08:07 07:55:18 CDT



AA-4B - 2025:08:07 07:55:37 CDT

August 7 views show multiple containers and active work at the roof edge near grocery receiving. These images support the continuing-project chronology and a request for the precise scope and controls used after the positive mastic result.

Plate AA-5: Conditions through August 19



AA-5A - 2025:08:16 09:22:01 CDT



AA-5B - 2025:08:19 09:14:11 CDT

The August 16 photograph shows a yellow roll-off and stacked material. The August 19 photograph shows multiple filled roll-offs and a telehandler. Together they document that exterior material-handling conditions continued into the second half of August.