Additional roof-work and material-handling views

SELECTION

Six photograph plates from the August 19, 2026 asbestos complaint binder: U-2 and U-5 through U-9. Printed dates range from August 3 to August 11, 2025. These add views to earlier selections; several show the same sequences as MB10 and must not be counted as separate incidents.

SOURCE AND DATES

Original PDF pages 107, 110, 111, 112, 113 and 114. The saved binder checksum was verified. The embedded images have no capture-date metadata, and matching original camera files were not located in this pass. Printed times are therefore the source author's labels, not independently verified dates.

PRIVACY TREATMENT

The vehicle license plate on U-6 (original PDF page 111) is permanently redacted. All other visible source content is preserved. Image/PDF metadata, links and annotations are removed. Source footers describing unaltered originals do not describe this redacted reading copy.

MEANING AND LIMITS

Captions are the submitter's descriptions, not agency findings. A still image does not establish load movement, material composition, asbestos exposure, events outside the frame or a regulatory violation.

LATER AGENCY EXPLANATION

DSHS's September 3, 2026 response says the evidence was insufficient to support a notification violation. It reports the inspector's account that asbestos-positive flashing was outside the then-current work area. DSHS issued the survey-related NOV. Those qualifications remain necessary when discussing these earlier images.



U-2 August 3, 2025, 9:14:30 a.m. (UTC−05:00) · IMG_1770.jpeg

Building perimeter. An open roll-off waste container and an adjacent portable sanitation unit are staged at the edge of the paved area, with stacked material visible behind the container. Photographed from a public vantage point.

The photograph does not identify the contents of the container.

Photograph reproduced without alteration. Native file retained; SHA-256 listed in the photo log at binder pp. 94-95.



U-5 August 5, 2025, 8:25:30 a.m. (UTC−05:00) · IMG_1907.jpeg

Telehandler with the boom extended to the roof edge, transferring a palletized load. Multiple workers are visible at the roof edge, with removed material and equipment staged along the parapet. Traffic cones stand at grade and a semi-trailer is at left. The submitter identifies the cream-colored masonry structure as the Garden Center building and associates it with the area of the later asbestos-positive sampling.

EPA is asked to confirm the sampling location against the survey and inspection records at Exhibits B and D. This photograph does not itself establish that correspondence, and no containment enclosure, regulated-area barrier, warning signage, or wetting equipment is identifiable from this vantage point.

Photograph reproduced without alteration. Native file retained; SHA-256 listed in the photo log at binder pp. 94-95.



U-6 August 5, 2025, 12:30:56 p.m. (UTC−05:00) · IMG_1915.jpeg

Auto Care and customer service frontage. Removed material, equipment, and an accumulation of dark debris are visible at and over the roof edge directly above the customer canopy, parked customer vehicles, and pennant flagging.

This documents proximity between roof-removal work and an occupied customer area. It does not identify the composition of the material shown.

Photograph reproduced without alteration. Native file retained; SHA-256 listed in the photo log at binder pp. 94-95.



U-7 August 7, 2025, 7:55:32 a.m. (UTC−05:00) · IMG_2019.jpeg

Continued roof work on August 7, 2025. Workers are visible along the roofline and equipment is staged at grade against the building. Photographed from a public vantage point.

Photograph reproduced without alteration. Native file retained; SHA-256 listed in the photo log at binder pp. 94-95.



U-8 August 7, 2025, 7:55:16 a.m. (UTC−05:00) · IMG_1997.jpeg

Same morning, opposite elevation. A telehandler and an open waste container are positioned against the building, with palletized material staged on the pavement.

The photograph does not identify the contents of the container.

Photograph reproduced without alteration. Native file retained; SHA-256 listed in the photo log at binder pp. 94-95.



U-9 August 11, 2025, 1:17:56 p.m. (UTC−05:00) · IMG_2233.jpeg

An open roll-off container, caution flagging strung between bollards, a portable sanitation unit marked JOTS RENTALS, and a large uncovered stack of removed board sheeting staged directly on unpaved ground at the building perimeter.

Removed material appears to be stored uncovered and in contact with soil. The photograph does not identify the composition of the stacked material.

Photograph reproduced without alteration. Native file retained; SHA-256 listed in the photo log at binder pp. 94-95.