Mt. Pleasant Fire Department

Occupancy: **WALMART**
Occupancy ID: **50A**
Address: **2311 JEFFERSON Mt. Pleasant TX 75455**

Form: MPFD Inspection Form - NEW

Inspection Type: **Reinspection**
Inspection Date: **1/9/2026** By: Evans, Charles
Time In: **14:56** Time Out: **21:00**
Authorized Date: **01/09/2026** By: Evans, Charles

Inspection Topics:

Building Exterior

Access to all secured gates blocking the fire lanes? 503.6

Can the fire department gain access through locked gates to get to fire lanes?

Status:
Notes:

Address number visible from street? 505.1

Is the address visible from street

Status:
Notes:

Key box installed 506.1

Do they have a lock box with keys to the occupancy?

Status:
Notes:

Maintain fire lanes? 503.3

Is the fire lanes marked and clearly identifiable?

Status:
Notes:

Provide access to FDC connections? 912.2.2

Can you gain access to the FDC in the event of a fire?

Status:
Notes:

Other

Violation not listed above:

Status:
Notes:

General Fire Protection

Certificate of occupancy clearly posted? 110

A certificate of occupancy must be displayed in public view.

Status:
Notes:

Decorative materials on ceilings? 807.1

there should be no decorative materials on the ceilings to promote fire spread or hamper sprinkler systems.

Status:
Notes:

Decorative materials/artwork on walls? 807.4.3.2

Decorative materials/artwork on walls must be of fire resistive materials

Status:
Notes:

Flammable/combustible stored properly? 3304.3.3

Flammable/combustible materials must be stored in proper containers.

Status:
Notes:

HVAC/Water heater storage area clean? 315.2.3

HVAC/Water heater storage must be clear of all combustibles.

Status:
Notes:

Proper storage of oily rags? 304.3.1

Oily rags and paint and rags with paint thinner need to be stored in proper containers.

Status:
Notes:

Secure gas cylinders by approved method? 3003.3.3

gas cylinders must be properly secured

Status:
Notes:

Other:

Violation not listed above:

Status:
Notes:

Other

Violation not listed above:

Status: PASS
Notes: All ceiling tiles that are missing throughout the store need to be replaced.

Corrected




Fire Protection Systems

Maintain sprinkler system? B903.1

Has the sprinkler system been maintain and kept in working order?

Status: PASS
Notes: This riser system is by the mechanic shop in the battery storage room. This riser was missed when getting an inspection and needs to be brought up to date.

Corrected 12/3/2024



Cooking vent a hood in place correctly? 904

is the vent a hood placed over the cooking surface correctly?

Status:
Notes:

Provide spare sprinkler heads and a wrench?

is there a spare sprinkler head for all types of heads on the system and a wrench to change them?

Status:
Notes:

Sprinkler heads free of decorations/hanging objects? 315.2.1

Is there any decorations or anything hanging from the sprinkler head?

Status:
Notes:

Sprinkler heads free of dust and or paint over spray? B903.1

Are the sprinkler heads clean and not painted?

Status:
Notes:

Storage clearance of 18 in. from sprinkler heads? 315.2.1

Is there 18 inches of clearance below sprinkler head?

Status:
Notes:

Vent a hood checked in the last 6 months? 904.11

Has the hood system been inspected in the last 6 months?

Status:
Notes:


Other

Violation not listed above:

Status: PASS
Notes: There is no way for the water to access the lower parts of the storage rack if something were to catch on fire. I would recommend wall mounted sprinkler heads or having a wire style storage racks.
Also there needs to be an (explosive) placard on the door of the room where the guns and ammo is stored.

Re visited on 12/3/2024. Still not taken care of.

Corrected as of 1-9-2026 The Sprinkler head has been relocated to point towards the wooden rack.
Note: Advised store manager to place a sign on the door entering the ammunition area stating "Live Ammunition"



Fire Extinguishers

Fire extinguisher for every 75 ft.? 906.3.1

occupant should not have to travel more than 75 feet any direction to get a fire extinguisher.

Status:
Notes:

Fire extinguishers in date? 906.1

Are all extinguisher up to date on inspection?

Status:
Notes:

Fire extinguishers mounted properly? 906.7

Are all the extinguishers mount at right height and proper location?

Status:
Notes:

Other

Violation not listed above:

Status:
Notes:

Alarm Systems

Equipment/system not removed or tampered with? 907

Has any or all the system been removed or tampered with that would cause the system not to work properly?

Status:
Notes:

Fire alarm system inspection in date? 907 (NFPA 72)

Has the alarm system been inspected by an alarm company and up to date on its required annual inspection?

Status:
Notes:

Fire alarm system installed properly? 907.2

is the fire alarm system installed in accordance with the fire code?

Status:
Notes:

Maintain fire alarm system in operable condition? 907

is the system maintained and kept in working order?

Status:
Notes:

Maintain fire alarm system testing records? 907

are they keeping up with all the testing records of the system?

Status:
Notes:

Other

Violation not listed above:

Status:
Notes:

Exits

Aisles Clear/Unobstructed? 2305.4

Are all the aisles clear and unobstructed for occupant egress?

Status:
Notes:

Emergency Lighting in place? 1006.1

Is there emergency lighting in place and in working order?

Status:
Notes:

Exit doors operable without a key? 1027.3

Does the exit open without having to unlock it?

Status:
Notes:

Exit doors swing outward? 1008.1.2

Do all exit doors swing in an outward direction?

Status:
Notes:

Exit doors/pathways unlocked and obscured? 1027.4

Is any of the exits or pathways blocked or locked?

Status:
Notes:

Exit goes through authorized area? 1014.2

Does the exit go through areas that are authorized for all occupants?

Status:
Notes:

Exit signs in proper locations? 1011.1

Is the exit signs in the right place and is there enough of them.

Status:
Notes:

Exit signs working properly? 1011.1

Are the bulbs working in the exit signs and you can see them when lights are off? and does battery backup work?

Status:
Notes:

fire escape plan posted? 408.8.1

Is there a fire escape plan posted where occupants can access it?


Status:
Notes:

Other

Violation not listed above:

Status: PASS
Notes: These doors are located in the photo lab. We ask that there is a "roof access " sign mounted here and on the fence that goes to the roof access ladder. Preferably a 12x12 sign with 2 inch letters.

Corrected as 1-9-2026



Electrical

Maintain 30 inch clearance to all electrical panels? 605.3

There has to be a 30 inch clearance around all panels.

Status: PASS
Notes: All breaker panels need to maintain an 30 inch clearance all the way around the panel from any combustibles.



Covers on electrical outlets and switches? 605.6

All electrical outlets and switches must have cover plates on them.

Status:
Notes:

Multi plug adapters compliant? 605.4

Multi plug adapters have to be compliant with fire code.

Status:
Notes:

Electrical Room and electrical panel properly labeled? 605.3.1

Are the breakers in the electrical panel labeled?

Status:
Notes:

open spaces in the breaker panel? 605.1 NFPA 70

is there any open spaces in the breaker panel

Status:
Notes:

Extension cord(s) properly used? (Temporary use only) 605.5

No Extension cord are to be used for permanent use.

Status:
Notes:

Portable, electric space heaters compliant? 605.10

Space heaters shall be of the right type and plugged in directly to an outlet.

Status:
Notes:

Other

Violation not listed above:

Status:
Notes:

Other

Violation not listed above:

Status:
Notes:

Hazardous Materials

Maximum Quantity Per Control Area? 2703.1

The maximum allowable quantity per control area

Status:
Notes:

MSDS are readily available on the premises? 2703.4

Material Safety Data Sheets shall be readily available

Status:
Notes:

Hazardous Identification Signs Posted? 2703.5

Visible hazard identification signs as specified in NFPA 704

Status:
Notes:

Other

Violation not listed above:

Status:
Notes:

Additional Time Spent on Inspection:

Category	Start Date / Time	End Date / Time

Notes: No Additional time recorded

Total Additional Time: 0 minutes

Inspection Time: 364 minutes

Total Time: 364 minutes

Summary:

Overall Result: Passed with Comments

Inspector Notes: Advised store manager to have a sign placed on the door into the ammunition room, stating "Live Ammunition"

Inspector:

Name: Evans, Charles
Rank: FF
Work Phone(s): None on file
Email(s): cevans@mpcity.org
Evans, Charles:




Signed on: 01/09/2026 15:01

Signature *Date*

Representative Signature:

Signature of: E-Mail on 01/09/2026 15:02



Signature *Date*