commenced without a valid, comprehensive asbestos survey or 10-day NESHAP notification. Suspect asbestos-bearing materials (asphalt-impregnated cover-boards and mastics) were released into the air during demolition and openly dumped in unsealed dumpsters and on the ground without HEPA containment, warning labels, or proper disposal manifests. Concurrently, no deck, dry-in, or final inspections were logged on the permit, and water leaks from the exposed roof allowed contaminated runoff into occupied sales areas—exposing workers, customers, and food products to serious health and safety hazards. [redacted] I can provide more evidence and documentation upon request. My PDF files are not able to upload on this platform.

Violation Still Occurring? Yes

State DEP/DEQ/DEM Notified? No

<20250630 - City of Mount Pleasant - Candias Webster - Records Email.jpg><20250627 - City of Mount Pleasant - Permit 35226.jpg><20250629 - Walmart Store 131 - Produce.jpg><20250629 - Walmart Store 131 - Strawberries.jpg><20250627 - City of Mount Pleasant - Walmart Store 131 - Asbestos Report.jpg><20250629 - Walmart Store 131 - Roof Debris (2).jpg><20250626 - Walmart Store 131 - Code Compliance Truck.jpg><20250625 - Walmart Store 131 - Roof Activity.jpg><20250628 - Walmart Store 131 - Roof Materials (1).jpg>