# Roof-project photographs: June 25-July 1, 2025

**SELECTION**

Eight original exhibit pages (Z-1 through Z-8) showing roof-project activity, containers and the receiving area. The project-sign photograph has contact details and site-rule text removed. All other visible source content is preserved.

**DATE AND SOURCE CHECK**

Printed capture times match the EXIF dates and time-zone offsets in the JPEG derivatives embedded in the source PDF. Their checksums match the source index. This confirms consistency within the saved package, not independent authentication of when or where the photographs were taken.

**LIMITS**

Photographs do not establish asbestos content, disturbance of asbestos-containing material, regulatory status, or events outside the frame. Original exhibit captions are the submitter's descriptions and requests, not agency findings.

**LATER AGENCY EXPLANATION**

DSHS's September 3, 2026 response says the evidence was insufficient to support a notification violation. It reports the inspector's account that the asbestos-positive flashing was outside the then-current work area. DSHS issued the survey-related NOV. These qualifications must accompany any use of the earlier photo allegations.

**COPY HANDLING**

Original page numbers are preserved. Hidden image metadata is removed where present; original binders and audit evidence remain private. The complete binder, other exhibits and original image files are outside this selection.

Source: September 3, 2026 evidence addendum, PDF pages 28, 29, 30, 31, 33, 34, 35, 36

Editorial context note. Source exhibits follow.

# Plate Z-1: Work activity before the inspection



Z-1A - 2025:06:25 14:38:50 CDT



Z-1B - 2025:06:28 09:26:20 CDT

The June 25 view shows a telehandler and roof-edge activity at the store. The June 28 view shows a work-zone container and portable toilet. Together they document project activity before the July 1 inspection without establishing the contents of the container or the composition of material handled on the roof.

# Plate Z-2: Yellow roll-off with sheet-like material




Z-2A - 2025:06:29 08:10:05 CDT




Z-2B - 2025:06:29 08:10:06 CDT

Two views show United Rentals roll-off 3420 with folded or curled dark sheet-like material extending above the rim. The photographs document a filled container two days before the inspection; they do not independently establish the asbestos content or regulatory classification of the material.

# Plate Z-3: Open roll-off containing roof-system debris



Z-3A - 2025:06:29 08:10:21 CDT



Z-3B - 2025:06:29 08:10:24 CDT

Close views show an open blue roll-off containing white rigid insulation boards, dark sheet-like pieces, green strapping, and other construction material. No liner is visible in the photographed upper/interior portions. The images do not establish that the contents were regulated asbestos-containing waste.

# Plate Z-4: Receiving-area context and project identification



Z-4A - 2025:06:29 08:10:51 CDT




Z-4B - 2025:06:29 08:11:11 CDT

The first view locates roll-offs and stored construction material along the building's receiving area. The second shows a DEEM project sign identifying Walmart Store 131 in Mount Pleasant, Texas. Read with Plates Z-2 and Z-3, these images link the June 29 container series to the project site.

# Plate Z-5: Filled blue roll-off - closer views




Z-5A - 2025:07:01 07:36:19 CDT




Z-5B - 2025:07:01 07:36:18 CDT

Two views show a blue Republic Services roll-off containing loose mixed material, including dark sheet-like pieces and metal items, with material extending to or above the rim. The photographs document availability of material for investigation on July 1; they do not independently establish that the contents were asbestos-containing roof waste.

# Plate Z-6: Filled blue roll-off - building context



Z-6A - 2025:07:01 07:36:18 CDT



Z-6B - 2025:07:01 07:36:18 CDT

Wider views locate the filled blue roll-off beside a trailer and the building's service/loading area. These views help establish site context and the presence of retained material on the inspection date, while preserving the same limits concerning composition and source.

# Plate Z-7: Orange roll-off and adjacent container



Z-7A - 2025:07:01 07:36:02 CDT



Z-7B - 2025:07:01 07:36:02 CDT

These views show an orange roll-off and an adjacent container in a separate exterior area along the building. The series supports the submitter's statement that more than one waste-container area existed onsite on July 1; it does not establish the contents or regulatory status of each container.

# Plate Z-8: Orange roll-off - additional site context



Z-8A - 2025:07:01 07:36:02 CDT



Z-8B - 2025:07:01 07:36:01 CDT

Additional views show the orange roll-off area, adjacent container, building exterior, and service access. Read together with the other Exhibit Z plates, the images support a focused request for DSHS to explain whether retained material was inspected, sampled, photographed, classified, or tracked to disposal.