Roof activity and material photographs

SELECTION

Two original exhibit pages (R-3 through R-6) showing material in a container, roof-edge activity, outdoor stacks and GAF EnergyGuard-labelled material on a trailer. The label is visible in the last photograph. These are reproduced source images with the submitter's captions.

DATE AND SOURCE CHECK

The source binder checksum was verified. Capture dates are not established by these downsampled PDF images. Original camera files and the derivative filenames printed on the plates have not been independently matched. A similar container view appears in MB09; it must not be counted as a separate event.

LIMITS

Photographs do not establish asbestos content, disturbance of asbestos-containing material, regulatory status, or events outside the frame. Original exhibit captions are the submitter's descriptions and requests, not agency findings.

LATER AGENCY EXPLANATION

DSHS's September 3, 2026 response says the evidence was insufficient to support a notification violation. It reports the inspector's account that the asbestos-positive flashing was outside the then-current work area. DSHS issued the survey-related NOV. These qualifications must accompany any use of the earlier photo allegations.

COPY HANDLING

Original page numbers are preserved. Hidden image metadata is removed where present; original binders and audit evidence remain private. The complete binder, other exhibits and original image files are outside this selection.

Source: August 19, 2026 asbestos complaint binder, PDF pages 90, 91


Editorial context note. Source exhibits follow.

PHOTO PLATE 2 OF 4



R-3 0A011349-F321-414F-B2E8-1A2B6A46BB60_1_105_c.jpeg

Closer view of removed roof-board material in an open project container.



R-4 D80EBAD6-7A56-44BD-BDEC-E110617DE337_1_105_c.jpeg

Workers handling roof-board material at the roof edge above the operating store frontage.

PHOTO PLATE 3 OF 4



R-5 96DF991C-E54B-44FB-81F8-800785F6F14A_1_105_c.jpeg

Stacks of removed dark roofing sheets and white board material stored outdoors.



R-6 27635148-CF8E-40C6-A194-5D5903F76CD6_1_105_c.jpeg

New GAF EnergyGuard 3-inch polyiso insulation packaging; useful for project identification and scale.

Original derivative filenames retained. Native files should be preserved separately for any metadata review.