MB22 - Additional roof-project photo plates

SELECTED PAGES

Four photographs on PDF pages 89 and 92 of the August 19, 2026 asbestos complaint binder (printed pages 79 and 82). The DEEM project sign is reproduced without redaction. In R-8, only the worker's face is masked; the worker, material stacks, vehicle interior and mirror are otherwise preserved.

SOURCE AND DATE LIMITS

The source binder checksum is verified. Exact capture dates and native camera files have not been established for these downsampled images. Similar views in other selections do not establish separate incidents.

WHAT THE PHOTOGRAPHS ESTABLISH

Captions are the submitter's descriptions. The photographs do not establish asbestos content, asbestos disturbance, disposal destination or regulatory violations.

LATER AGENCY EXPLANATION


DSHS's September 3, 2026 response says the evidence was insufficient to support a notification violation and reports that the asbestos-positive flashing was outside the then-current work area. DSHS issued the survey-related NOV. Retain these qualifications with the photographs.

COPY HANDLING

Original layout and captions are preserved. Only the worker-face area is removed. Selected pages are flattened to exclude hidden text, image metadata and editable objects. Original source files and the complete binder remain private.

PHOTO PLATE 1 OF 4

Context only — not proof of asbestos content or release



R-1 CCB673C3-6D39-4891-AE38-D788E918B56A_1_105_c.jpeg

Contractor contact sign identifying DEEM personnel and Walmart Store 0131 project.



R-2 80B1D8F0-A891-42E1-8E01-F9ABB8B17FDE_1_105_c.jpeg

Open container with removed white roof-board material and other project debris.

Original derivative filenames retained. Native files should be preserved separately for any metadata review.

PHOTO PLATE 4 OF 4



R-7 FEA68AC6-1E3E-46FA-A76D-790C8A746517_1_105_c.jpeg

Open Republic Services container with mixed non-roof debris visible at the loading area.



R-8 C530423F-9EFF-4A2A-AA81-36740D65C30E_1_105_c.jpeg

Worker beside outdoor stacks of removed white roof-board material and dark roofing sheets.